

New Gold Rainy River Mine Weekly Exceedance  
and Spill Report for Period Dec 23 - 30, 2019

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MECF
222585	Spill	New Gold	Korpi Road	24.12.2019 14:30	Hydraulic Fluid	Land	20 L	Grader travelling down Korp Road blew out hydraulic fluid line.	Shut down grader, placed spill pads on area. Then scraped up with wheel loader and placed contaminated material in hazardous soil bin at the process plant.	No	No

**New Gold Rainy River Mine Weekly Exceedance  
and Spill Report for August 12th - August 18th 2019**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MECP
219844	Spill	Contractor	Tom Veert	Veert Laydown	8/16/2019	Land	8L	Operator was fueling truck, he removed the nozzle before the fuel stopped spraying the rock around the truck	Spill pads were used, and gravel was placed into empty pails	No	No

**New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period October 7-13, 2019**

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable MECP
221060	Spill	New Gold	Assay Lab	10.10.2019 11:50 am	Lead Dust	Land	10 kg	Approximately 10 kg of lead dust escaped during filter changover, covering floor of scaffolding and ground surface between assay lab and employee parking lot.	Dust was cleaned up using laboratory grade vacuum and contained into sealed plastic bag. Contaminated gravels were shoveled into plastic pails. GFL removed plastic bag and pails from site.	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period Oct 28 to Nov 3, 2019

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable MECP
221380	Spill	Contractor	Equipment Laydown	10.28.2019 10:30 pm	Hydraulic Oil	Land	75L	Oil leak occurred during tire mounting, dismounting, maintenance activities and movement of tire components around the yard using Komatsu Loader.	Supervisor placed spill pads onto hydraulic oil on ground. Hydrocarbon contaminated soils and gravels plus spill pads were removed and placed into GFL bins for removal from site.	No

New Gold Rainy River Mine Weekly Exceedance and Spill Report for Period Nov 11-17, 2019

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable MECP
221769	Spill	Contractor	EMRS - Crusher Access Road	11.17.2019 09:15 am	Hydraulic fluid	Land	4 - 5 L	Operator was spreading gravel on the road and ramp with an excavator. He curled the bucket and the hydraulic hose broke.	Operator stopped equipment and contained the spill using spill kit. A Mechanic was sent to repair the unit. Once repair is completed, the contaminated material and pads will be cleaned up and removed from site.	No

New Gold Rainy River Mine Weekly Exceedance  
and Spill Report for Period Dec 23 - 30, 2019

INX #	SPILL REPORT	New Gold or Contractor	Spill Origin	Date and Time Reported	Product Spilled	Impact	Quantity	Description & Cause	Remediation & Disposal	Externally Reportable SAC	Externally Reportable MECF
222585	Spill	New Gold	Korpi Road	24.12.2019 14:30	Hydraulic Fluid	Land	20 L	Grader travelling down Korp Road blew out hydraulic fluid line.	Shut down grader, placed spill pads on area. Then scraped up with wheel loader and placed contaminated material in hazardous soil bin at the process plant.	No	No