



Appendix IR1-11-A

Photos of Bitter Creek

Red Mountain Underground Gold Project
IDM Mining Ltd. Responses to
Canadian Environmental Assessment Information Request #1



Photo 1: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), May 16, 2017



Photo 2: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), August 22, 2017



Photo 3: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), November 8, 2017



Photo 4: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), showing thalweg on river left (looking upstream) May 16, 2017



Photo 5: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), showing side channel on river right (looking upstream) May 16, 2017



Photo 6: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), looking upstream at side channel, October 18, 2017



Photo 7: Bitter Creek Road Interference Area (station 4+550 m to 4+840 m), looking upstream at side channel, November 8, 2017